

Monday 21st June, 2021


Dear Customer,

Re: Product Change Notification for Harwin product.

Please be advised that a few dimensions relating to male Gecko Latch horizontal connectors have changed by a small amount. The affected parts are in the following ranges:

- G125-MHXXX05L1P & R
- G125-MHXXX05L3P & R
- G125-MHXXX05L6P & R
- G125-MHXXX05L2P & R
- G125-MHXXX05L5P & R
- G125-MHXXX05L7P & R

The dimensional changes can be seen in these two extracts from the Technical Drawings:





Product is already stocked and manufactured to the revised dimensions. The Technical Drawings have been updated on the website – catalog revisions will follow at a later date.

Please see the attached spreadsheet for a more detailed list of affected items, also available in Excel format here:

https://cdn.harwin.com/pdfs/PCN_spreadsheet_21-Jun-2021.xlsx

If you have any further questions regarding this letter, please do not hesitate to contact us.

Yours faithfully,

The Product Change Team

technical@harwin.com

Product Change Notification from Harwin

Part number affected	Drawing showing new dimensions
G125-MH10605L1P	G125-MHXXX05L1P.pdf
G125-MH10605L1R	G125-MHXXX05L1R.pdf
G125-MH10605L3P	G125-MHXXX05L3P.pdf
G125-MH10605L3R	G125-MHXXX05L3R.pdf
G125-MH10605L5P	G125-MHXXX05L5P.pdf
G125-MH10605L5R	G125-MHXXX05L5R.pdf
G125-MH10605L7P	G125-MHXXX05L7P.pdf
G125-MH10605L7R	G125-MHXXX05L7R.pdf
G125-MH11005L1P	G125-MHXXX05L1P.pdf
G125-MH11005L1R	G125-MHXXX05L1R.pdf
G125-MH11005L3P	G125-MHXXX05L3P.pdf
G125-MH11005L3R	G125-MHXXX05L3R.pdf
G125-MH11005L5P	G125-MHXXX05L5P.pdf
G125-MH11005L5R	G125-MHXXX05L5R.pdf
G125-MH11005L7P	G125-MHXXX05L7P.pdf
G125-MH11005L7R	G125-MHXXX05L7R.pdf
G125-MH11205L1P	G125-MHXXX05L1P.pdf
G125-MH11205L1R	G125-MHXXX05L1R.pdf
G125-MH11205L3P	G125-MHXXX05L3P.pdf
G125-MH11205L3R	G125-MHXXX05L3R.pdf
G125-MH11205L5P	G125-MHXXX05L5P.pdf
G125-MH11205L5R	G125-MHXXX05L5R.pdf
G125-MH11205L7P	G125-MHXXX05L7P.pdf
G125-MH11205L7R	G125-MHXXX05L7R.pdf
G125-MH11605L1P	G125-MHXXX05L1P.pdf
G125-MH11605L1R	G125-MHXXX05L1R.pdf
G125-MH11605L3P	G125-MHXXX05L3P.pdf
G125-MH11605L3R	G125-MHXXX05L3R.pdf
G125-MH11605L5P	G125-MHXXX05L5P.pdf
G125-MH11605L5R	G125-MHXXX05L5R.pdf
G125-MH11605L7P	G125-MHXXX05L7P.pdf
G125-MH11605L7R	G125-MHXXX05L7R.pdf
G125-MH12005L1P	G125-MHXXX05L1P.pdf
G125-MH12005L1R	G125-MHXXX05L1R.pdf
G125-MH12005L3P	G125-MHXXX05L3P.pdf
G125-MH12005L3R	G125-MHXXX05L3R.pdf
G125-MH12005L5P	G125-MHXXX05L5P.pdf
G125-MH12005L5R	G125-MHXXX05L5R.pdf
G125-MH12005L7P	G125-MHXXX05L7P.pdf
G125-MH12005L7R	G125-MHXXX05L7R.pdf
G125-MH12605L1P	G125-MHXXX05L1P.pdf
G125-MH12605L1R	G125-MHXXX05L1R.pdf
G125-MH12605L3P	G125-MHXXX05L3P.pdf
G125-MH12605L3R	G125-MHXXX05L3R.pdf
G125-MH12605L5P	G125-MHXXX05L5P.pdf
G125-MH12605L5R	G125-MHXXX05L5R.pdf
G125-MH12605L7P	G125-MHXXX05L7P.pdf
G125-MH12605L7R	G125-MHXXX05L7R.pdf
G125-MH13405L1P	G125-MHXXX05L1P.pdf
G125-MH13405L1R	G125-MHXXX05L1R.pdf
G125-MH13405L3P	G125-MHXXX05L3P.pdf
G125-MH13405L3R	G125-MHXXX05L3R.pdf
G125-MH13405L5P	G125-MHXXX05L5P.pdf
G125-MH13405L5R	G125-MHXXX05L5R.pdf
G125-MH13405L7P	G125-MHXXX05L7P.pdf
G125-MH13405L7R	G125-MHXXX05L7R.pdf
G125-MH15005L1P	G125-MHXXX05L1P.pdf
G125-MH15005L1R	G125-MHXXX05L1R.pdf
G125-MH15005L3P	G125-MHXXX05L3P.pdf
G125-MH15005L3R	G125-MHXXX05L3R.pdf
G125-MH15005L5P	G125-MHXXX05L5P.pdf
G125-MH15005L5R	G125-MHXXX05L5R.pdf
G125-MH15005L7P	G125-MHXXX05L7P.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new dimensions
G125-MH15005L7R	G125-MHXXX05L7R.pdf
G125-MH20605L2P	G125-MHXXX05L2P.pdf
G125-MH20605L2R	G125-MHXXX05L2R.pdf
G125-MH20605L3P	G125-MHXXX05L3P.pdf
G125-MH20605L3R	G125-MHXXX05L3R.pdf
G125-MH20605L6P	G125-MHXXX05L6P.pdf
G125-MH20605L6R	G125-MHXXX05L6R.pdf
G125-MH20605L7P	G125-MHXXX05L7P.pdf
G125-MH20605L7R	G125-MHXXX05L7R.pdf
G125-MH21005L2P	G125-MHXXX05L2P.pdf
G125-MH21005L2R	G125-MHXXX05L2R.pdf
G125-MH21005L3P	G125-MHXXX05L3P.pdf
G125-MH21005L3R	G125-MHXXX05L3R.pdf
G125-MH21005L6P	G125-MHXXX05L6P.pdf
G125-MH21005L6R	G125-MHXXX05L6R.pdf
G125-MH21005L7P	G125-MHXXX05L7P.pdf
G125-MH21005L7R	G125-MHXXX05L7R.pdf
G125-MH21205L2P	G125-MHXXX05L2P.pdf
G125-MH21205L2R	G125-MHXXX05L2R.pdf
G125-MH21205L3P	G125-MHXXX05L3P.pdf
G125-MH21205L3R	G125-MHXXX05L3R.pdf
G125-MH21205L6P	G125-MHXXX05L6P.pdf
G125-MH21205L6R	G125-MHXXX05L6R.pdf
G125-MH21205L7P	G125-MHXXX05L7P.pdf
G125-MH21205L7R	G125-MHXXX05L7R.pdf
G125-MH21605L2P	G125-MHXXX05L2P.pdf
G125-MH21605L2R	G125-MHXXX05L2R.pdf
G125-MH21605L3P	G125-MHXXX05L3P.pdf
G125-MH21605L3R	G125-MHXXX05L3R.pdf
G125-MH21605L6P	G125-MHXXX05L6P.pdf
G125-MH21605L6R	G125-MHXXX05L6R.pdf
G125-MH21605L7P	G125-MHXXX05L7P.pdf
G125-MH21605L7R	G125-MHXXX05L7R.pdf
G125-MH22005L2P	G125-MHXXX05L2P.pdf
G125-MH22005L2R	G125-MHXXX05L2R.pdf
G125-MH22005L3P	G125-MHXXX05L3P.pdf
G125-MH22005L3R	G125-MHXXX05L3R.pdf
G125-MH22005L6P	G125-MHXXX05L6P.pdf
G125-MH22005L6R	G125-MHXXX05L6R.pdf
G125-MH22005L7P	G125-MHXXX05L7P.pdf
G125-MH22005L7R	G125-MHXXX05L7R.pdf
G125-MH22605L2P	G125-MHXXX05L2P.pdf
G125-MH22605L2R	G125-MHXXX05L2R.pdf
G125-MH22605L3P	G125-MHXXX05L3P.pdf
G125-MH22605L3R	G125-MHXXX05L3R.pdf
G125-MH22605L6P	G125-MHXXX05L6P.pdf
G125-MH22605L6R	G125-MHXXX05L6R.pdf
G125-MH22605L7P	G125-MHXXX05L7P.pdf
G125-MH22605L7R	G125-MHXXX05L7R.pdf
G125-MH23405L2P	G125-MHXXX05L2P.pdf
G125-MH23405L2R	G125-MHXXX05L2R.pdf
G125-MH23405L3P	G125-MHXXX05L3P.pdf
G125-MH23405L3R	G125-MHXXX05L3R.pdf
G125-MH23405L6P	G125-MHXXX05L6P.pdf
G125-MH23405L6R	G125-MHXXX05L6R.pdf
G125-MH23405L7P	G125-MHXXX05L7P.pdf
G125-MH23405L7R	G125-MHXXX05L7R.pdf
G125-MH25005L2P	G125-MHXXX05L2P.pdf
G125-MH25005L2R	G125-MHXXX05L2R.pdf
G125-MH25005L3P	G125-MHXXX05L3P.pdf
G125-MH25005L3R	G125-MHXXX05L3R.pdf
G125-MH25005L6P	G125-MHXXX05L6P.pdf
G125-MH25005L6R	G125-MHXXX05L6R.pdf

Product Change Notification from Harwin

Part number affected	Drawing showing new dimensions
G125-MH25005L7P	G125-MHXXX05L7P.pdf
G125-MH25005L7R	G125-MHXXX05L7R.pdf